


Collision repair estimate

Right front damage on a 2022 compact SUV, for insurance claim KM-26-448172.

BRANDY WINE COLLISION CENTER

ESTIMATE # BWC-E-26-1906
ISSUED Dec 2, 2026
VALID UNTIL Jan 2, 2027

PREPARED BY

Brandywine Collision Center
Tony Russo
+1 302 555 0146
tony@brandywinecollision.example

PREPARED FOR

Rachel Kim
Rachel Kim
+1 302 555 0181
rachel.kim@mail.example
Claim: Keystone Mutual #KM-26-448172

Estimate summary

Written after a full teardown inspection on December 1. If hidden damage is found during repair, we send a supplement to your insurer before doing the work.

ESTIMATED TOTAL
$4,632.00
Parts and labor

INSURER PAYS
$4,132
Total less your deductible

YOU PAY
$500
Your deductible

REPAIR TIME
5 days
Once parts arrive


PARTS
OEM
New, from the manufacturer

WARRANTY
Lifetime
On workmanship and paint

Vehicle and claim

DETAIL	RECORD
Vehicle	2022 compact SUV, AWD, blue metallic
VIN	...7Z41188 (last 7)
Odometer	31,406 miles
Insurer	Keystone Mutual, adjuster Paul Grant
Claim	KM-26-448172, collision, $500 deductible
Date of loss	November 26, 2026


OEM parts on order



Bumper cover

Primed by the factory, painted by us to match your car's color code.

Due	Dec 7



LED headlamp


The complete assembly, aimed after fitting.

Due	Dec 7

Made with ExtraflowDoc

extraflowdoc.com

Damage found



The impact pushed in the bumper and grille, broke the right headlamp and creased the fender. The structure measured within factory tolerance, so no frame straightening is needed.

Panel by panel

#	PART	DAMAGE	REPAIR
1	Bumper, grille, absorber	Cracked cover, absorber crushed	Replace
2	Right headlamp	Lens and mounting tabs broken	Replace
3	Right fender	Crease along the wheel arch	Replace and refinish
4	Front radar and camera	Moved with the grille	Calibrate
—	Right front door	No damage	Blend paint only

Made with ExtraflowDoc extraflowdoc.com

Estimate

Body and refinish labor $68 an hour; structural $85 an hour.

#	ITEM	QTY	PRICE	DISC.	TAX	TOTAL
	Parts					
1	**Front bumper cover, OEM, primed** Code: P-BMP	1 part	$612.00	–	0%	$612.00
2	**Front bumper energy absorber, OEM** Code: P-ABS	1 part	$148.00	–	0%	$148.00
3	**Right headlamp assembly, LED, OEM** Code: P-HLR	1 part	$1,045.00	–	0%	$1,045.00
4	**Grille assembly with radar cover** Code: P-GRL	1 part	$389.00	–	0%	$389.00
5	**Right front fender, OEM** Code: P-FDR	1 part	$428.00	–	0%	$428.00
6	**Emblem, clips and fasteners kit** Code: P-CLP	1 kit	$46.00	–	0%	$46.00
				Subtotal: Parts		**$2,668.00**
	Labor and services					
7	**Body labor: remove, replace and align panels** Code: L-BDY	9.5 hours	$68.00	–	0%	$646.00
8	**Refinish labor: fender, bumper and blend door** Code: L-REF	6.8 hours	$68.00	–	0%	$462.40
9	**Paint and materials** Code: L-MAT	6.8 hours	$42.00	–	0%	$285.60
10	**Structural measurement, front** Code: L-FRM	1 hour	$85.00	–	0%	$85.00
11	**Front radar and camera calibration (ADAS)** Code: S-ADAS	1 job	$350.00	–	0%	$350.00
12	**Four-wheel alignment, sublet** Code: S-ALN	1 job	$129.00	–	0%	$129.00
13	**Hazardous waste disposal** Code: S-HAZ	1 fee	$6.00	–	0%	$6.00
				Subtotal: Labor and services		**$1,964.00**

Subtotal	$4,632.00
Sales tax (none in Delaware)	$0.00
Estimated total	**$4,632.00**

Made with ExtraflowDoc

extraflowdoc.com

Who pays what

Your insurer has approved this estimate. You pay only your deductible, when you collect the car.

	AMOUNT
Estimate total	$4,632.00
Your deductible	$500.00
Paid by Keystone Mutual directly to us	$4,132.00

Your repair

Parts are due on December 7. We text you at each step.

Dec 7 ○ **Parts in**

Checked against the estimate.

Dec 8 ○ **Body work**

Bumper, grille, headlamp and fender fitted.

Dec 9–10 ○ **Paint**

Fender and bumper painted, door blended.

Dec 11 ○ **Calibrate and align**

ADAS calibration and alignment, road test.

Dec 12 ○ **Ready**

Washed, inspected and ready to collect.

Made with ExtraflowDoc

extraflowdoc.com

Warranty

COVERAGE

Workmanship: Lifetime, while you own the car

Paint: Lifetime against peeling and fading

Parts: Manufacturer warranty, 12 months or more

NOT COVERED

- New damage, wear and tear
- Rust from untreated chips after delivery

HOW TO CLAIM

1. Bring the car and this estimate number
2. We inspect it the same day

Repair authorization terms

1. Supplements

1.1 Hidden damage found after teardown is photographed and sent to your insurer as a supplement. We do not do the extra work until it is approved.

2. Parts

2.1 This estimate uses new OEM parts. Your policy may allow other parts; we will tell you before any change.

3. Storage

3.1 The car may be collected for 3 days after we tell you it is ready. After that, storage is $40 a day.

4. Rental

4.1 Your policy includes a rental car. We book it for the repair days.

Repair authorization

I authorize Brandywine Collision Center to repair my vehicle as described in this estimate and to receive payment from my insurer.

COMPANY Rachel Kim

OWNER NAME _____

SIGNATURE _____

DATE _____

PHONE FOR UPDATES _____

Made with ExtraflowDoc extraflowdoc.com